


**Scenario # 3;** Infrared used to determine structural cell fill on a concrete block home



The exterior walls of the home were scanned with infrared cameras and the images indicate that the exterior walls appear to be insulated, the 1<sup>st</sup> floor concrete block wall cells appear to be filled as required, and no evidence of water intrusion was indicated at the time of this inspection.

The engineered plans must be consulted to verify actual cell block fill specs/requirements.



Pictured above is an example of the infrared imaging conducted on the exterior of a concrete block house.